

## TECHNICAL BULLETIN

► *Recommend Earliest Possible Action* ◀



[www.mceinc.com](http://www.mceinc.com)

**Reference**            **118A**  
Route to                **Service Manager/Modernization Manager/Construction Manager**  
From                    MCE Technical Support Department  
Date                    January 15, 2001  
Pages                   1  
Enclosures            Relay module, wiring diagram and instructions

**Subject**              **MagneTek HPV900-XXXX-0E1-C1 Drive / Series M AC Controller**

**Description**        The Magnetek modified design of the Magnetek Model C1 Drive requires the use of multiple directional relays. As of June 27, 2000 MCE has incorporated multiple directional relays into the Series M AC Magnetek HPV900 Controller.

**Action**                Install UAX/DAX relay module (Mod Kit 118A) and wire to the dedicated directional inputs on the Magnetek drive. This prevents the car from operating in a direction opposite than intended. Change the hi-lighted parameters as shown on the attached instructions.

**MCE Help**            As always, should you require technical assistance on other issues:  
                              ! Telephone 916/463-9200  
                              ! Touch "6" for Technical Support  
                              ! **Refer to the reference number above**