

TECHNICAL BULLETIN

► *Recommend Earliest Possible Action* ◀



www.mceinc.com

Reference **118B**
Route to **Service Manager/Modernization Manager/Construction Manager**
From MCE Technical Support Department
Date January 15, 2001
Pages 1
Enclosures Relay module, wiring diagram and instructions

Subject **MagneTek HPV900-XXXX-0E1-C1 Drive / Series M AC Controller**

Description The Magnetek modified design of the Magnetek Model C1 Drive requires the use of multiple directional relays. As of June 27, 2000 MCE has incorporated multiple directional relays into the Series M AC Magnetek HPV900 Controller.

Action Install UAX/DAX/DZX relay module (Mod Kit 118B) and wire to the dedicated directional inputs on the Magnetek drive. This prevents the car from operating in a direction opposite than intended and from picking high leveling speed when the car is in the door zone. Change the hi-lighted parameters as shown on the attached instructions.

MCE Help As always, should you require technical assistance on other issues:

- ! Telephone 916/463-9200
- ! Touch "6" for Technical Support
- ! **Refer to the reference number above**