

TECHNICAL BULLETIN

► *Take Action During Your Next Visit* ◀



www.mceinc.com

Reference 121
Route to **Service Manager/Modernization Manager/Construction Manager**
From MCE Technical Support Department (916/463-9200 then touch 6)
Date June 18, 2001
Pages 1
Enclosures EPROM replacement instructions

Subject **Required Controller Software Upgrade Applying ONLY to the list of Jobs Attached**

Description Version Release 4. IMC and Non-IMC Controller

Release 4 software is released as a routine production upgrade intended to provide consistent user interface across most MCE product lines. Release 4 enhancements are documented in the respective product manuals.

Release 3 software was installed in Group M3, and IMC controls shipped prior to 6/5/01. All shipments made after 6/5/01 will have Release 4 software in the Group M3, IMC and Non-IMC Controllers (with the exception of the IMC-MG and Programmable Controllers). Release 3 software installed on existing controllers will not operate with Release 4 M3 Group or Local Controllers.

Action If you received this bulletin, you have one (or more) controllers that have Release 3 software and must be replaced with Release 4. For the list of jobs attached, one set of EPROMs and the appropriate manual has been enclosed for each Group or Controller that require replacement, along with instructions. These Release 3 Groups and Controllers must be upgraded prior to integrating a Group with Release 4 equipped Controllers.

MCE Help Should you require technical assistance on this or any other issue:
! Telephone 916/463-9200
! Touch "6" for Technical Support
! **Refer to the reference number above**