

Reference **102**
Route to **Service Manager**
From Ray Galvan, MCE Technical Support Manager
Date July 10, 1996
Pages 3 pages via fax transmission
Enclosures Letter from GE; enlarged view illustration

Subject **GE Starter Inspection Recommended**

Description **Retorque Contactor Screws**
The GE CA5F contactors used with **MCE** hydraulic, DC and AC controllers may have stationary contact screws that were not properly torqued by GE during the manufacturing process. See attached reference letter from General Electric Electrical Distribution & Control.

Action The **screws** holding the stationary contacts **need to be inspected and tightened** (if necessary) during your next scheduled maintenance. A drawing of the contactor has been provided with the location of the six screws and the torque requirements indicated.

Help Should you require additional technical assistance:

- Telephone 916/638-4011
- Touch "2" for Technical Support
- **Refer to the reference number above**